14-COLUM.Y

HISTORIC AMERICAN ENGINEERING RECORD

INDEX TO PHOTOGRAPHS

SIMPSONVILLE MILL

West side of Cedar Lane at Guilford Road Columbia vicinity

Howard County

Maryland

MD-91-11

Photographer: John P. Herr

October 1992

HAER No. MD-91

MD-91-1	MILL, HEADRACE, AND TAILRACE. CONTEXTUAL VIEW FROM NORTHWEST.
MD-91-2	MILL, WHEELPIT WALL, AND WHEELPIT. VIEW FROM SOUTHWEST.
MD-91-3	MILL, WHEELPIT WALL, AND WHEELPIT. VIEW FROM SOUTH.
MD-91-4	MILL. VIEW OF SOUTHEAST FACADE.
MD-91-5	MILL. CONTEXTUAL VIEW FROM NORTH.
MD-91-6	MILL. DETAIL OF ARCHED SHAFTWAY FROM SOUTHWEST.
MD-91-7	MILL. INTERIOR VIEW FROM SOUTHEAST.
MD-91-8	MILL. DETAIL OF SOUTHWEST DOOR LINTELS FROM EAST.
MD-91-9	MILL. INTERIOR VIEW OF SOUTHEAST CORNER SHOWING CHIMNEY FLUE.
MD-91-10	HEADGATE. VIEW FROM SOUTHWEST.

HEADRACE AND WHEELPIT WALL. VIEW FROM SOUTHEAST.

